



Legend

- Dam Embankments
- DSDA Pond Inundation Area

Note:
Because of the methods, procedures, and assumptions used to determine the flooded areas — the limits of flooding shown are approximate and should be used only as a guideline for establishing evacuation zones. Areas inundated in an actual event will depend on actual failure conditions and may differ from areas shown on the maps.



Date: Jun 03 2011 11:01:02 AM User: BHarter
File: F:\Inundation\400 19 00\Design\Civil\GIS\DSDA_Pond_Inundation_Map.mxd



REVISIONS:

**PAPE-DAWSON
ENGINEERS**

555 EAST RAMSEY | SAN ANTONIO, TEXAS 78216 | PHONE: 210.375.9000
FAX: 210.375.5010

TEXAS BOARD OF PROFESSIONAL ENGINEERS, FIRM REGISTRATION # 470

**DSDA Pond
Dam Breach
Inundation Map**

JOB NO.	400-19-00
DATE	Jun 2011
DESIGNER	JML
CHECKED	RH
DRAWN	JML
SHEET	1